



4 Optitap © for Patching and Splicing
P/N: FSPED12124141-1057-RS-4OSPSCA

Materials Include:

- (1) Splice Tray Holder
- (2) Cable Clamps (optional)
- (1) 4 Optitap© Adapter Plate
- (4) 4 x 2 mm long Yellow Jacket Pigtails for Splicing
- (1) Ground Bar with #6 Ground Wire Clamp**
- (2) 15" Ground Straps**
- (1) 16" X 16" Vapor Barrier
- (7) Medium Wire Saddles
- (1) Generic 811 Warning Label**

Optional MSI SI-GL4-11 Clamp
 Optional One 15" Ground Strap
 5 1/4-20 Keps Nuts with Cable Clamps
 You may also use your own company label

Hardware for 2 x 2 Kit Bag:

- (5) 1/4-20 Keps Nuts**
- (1) 1/4-20x1/2" Carriage Bolts
- (2) 10-24 Keps Nuts
- (2) 10-24x1/2" Carriage Bolts
- (2) 10-32x5/8" Phil Pan Screws

Subject to type availability. Some variations may have limited stock or may be subject to minimum order quantity.

