



**8" HDPE solid base pedestal configured for expressing and splicing only
(splice tray not included).**

P/N: FSPL08082537-1001-RS-ST

Materials Needed:

- (1) Splice Tray Holder
- (1) 14" Velcro Strap
- (2) Cable Clamps
- (1) Ground Bar with #6 Tab
- (1) 15" Ground Straps
- (1) 8" Flat Bracket for tying of cables
- (3) 8" Pedestal Splice Tray Brackets
- (1) 16" X 16" Vapor Barrier
- (2) Large Round Wire Saddles
- (1) Medium Wire Saddle

Hardware for 2 x 2 Kit Bag:

- (6) 1/4-20 x 1/2" Carriage Bolts
- (4) 1/4-20 Keps Nuts
- (2) 10-20 x 1/2" Carriage Bolts
- (2) 10-20 Keps Nuts
- (2) 8-32 x 3/8" Phil Pan Screws
- (2) 8-32 Keps Nuts

Subject to type availability. Some variations may have limited stock or may be subject to minimum order quantity.

